




CHISELED ROSE DRAIN

Chiseled Rose Drain - [NO OVERFLOW]

Bonde de lababo Rose sans trop plein

Ref #: 13201496



Copyright © Compas 2010 www.compassstone.com

Can be cut for adjustment on site

* DRILLING = Ø 1 ³/₄"

 COMPAS™